



## Instructions for re-scanning Sansonic or Lasonic Converter Boxes

\*With converter box on, press CH SCAN button on remote

\*Press ENTER or OK